



EPILOG LASER

16371 Table Mountain Parkway

Golden, Colorado 80403

Phone 303-215-9171 - FAX 303-277-9669

www.epiloglaser.com

Procedure Title: Replacing the Rim style rotary motor


Machine Type: Fusion

Intro:


This procedure details steps to replacing the Rim style rotary motor.

Procedure:

1. Unplug the motors connector



2. Remove screws holding the motor in place, the motor can now be removed



3. Reverse steps 2 – 1 to install the new motor.

If you have any questions, please contact Epilog's Technical Support

Phone 303.215.9171

Fax 303.531.7594

E-Mail tech@epiloglaser.com